

BELZONA® REBUILDS ERODED CORRODED TAILSHAFT

CUSTOMER

TUG BOAT OPERATOR
Vancouver, BC

APPLICATION DATE

August 1996

PROBLEM

Sever corrosion had eroded the seal area of the tail shaft.

PRODUCTS

Belzona® 1111 Super Metal.

SUBSTRATE

Mild steel.

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflets MPT-1

BELZONA FACTS

Using Belzona® enabled the tug boat operator to extend the life of the shaft for many more years.

PHOTOGRAPHS

1. Shaft set up in lathe after under cutting and grit blasting
2. Application of Belzona® 1111 in progress.
3. 1st cut in progress.
4. Completed shaft repair

